








A		6,0x30	20
B		4,0x40	04
C		7,0x50	04
D		350mm	04
E		3,5x30	04
F		10x10	50
G		Chave zeta 4mm	01
H		Cantoneira metal 22x22	12
J		Puxador 1 ponto	04
K		13x15	16
L		Bisnaga de cola	01
M		Pé palito madeira 170mm	04
N		3,5x14	64



Montagem gaveta

